Neighborhood, House 468-470 N. St. S.W. Washington, D.C.

HABS NO. DC-128 HABS D.C WASH

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA .
District of Washington D.C.

Historic American Buildings Survey Delos H. Smith, District Officer 1707 Eye St. N.W., Washington D.C. ADDENOUN FOLLOWS...

Addendum to
Duncanson-Cranch House (Barney Neighborhood House)
468-470 N Street, SW
Washington
District of Columbia

HABS No. DC-128

HABS DC, WASH,

## **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240

Form 10—920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS DC, WASH,

## ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VIC	INITY	
District of Columbia		Washington			
HISTORIC NAME OF STRUCTURE (INCL	UDE SOURCE FOR	NAME)		HABS NO.	
Duncanson- Cranch House			DC-128		
SECONDARY OR COMMON NAMES OF STRUCTURE					
Barney Neighborhood House					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
468-470 N Street, SW					
			ARCHITECT(S) (INCLUDE SOURCE) attributed to William Levering, architect		
ca. 1794-1795 for the Greenleaf Syndic			af Syndicat	e	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)					
Interesting example of the Federal Style. From 1904 to 1960 was the headquarters for Barney Neighborhood House.					
STYLE (IF APPROPRIATE) Federal					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
Brick, with stone trim SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS DN SEPARATE PAGES ARE ACCEPTABLE)					
Double house designed to appear as a single unit; 44' facade (6-bays); 3-stories;					
raised basement; gable roof					
EXTERIOR FEATURES OF NOTE					
2nd-story windows set in stuccoed blind arches; splayed stone lintels; paired modillion cornice; belt course below second floor; entrances on sides; west side entrance has semi-					
circular fanlight and is flanked by semicircular arched windows in sunken arches					
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NDT SKETCHED)					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES					
Rehabilitated 1964-1966 as part of Harbour Square urban renewal development.					
PRESENT CONDITION AND USE					
Condition in 1974 good.					
OTHER INFORMATION AS APPROPRIATE					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
Schwartz, Nancy B. Historic American Buildings Survey District of Columbia Catalog, 1974.					
Listed on National Register of Historic Places.					
Category II District of Columbia Landmark.					
COMPILER, AFFILIATION				DATE	
Alison K. Hoagland, H	IABS (edited by	Druscilla J. Nul	1, HABS) [	6/24/83	